



Afløbsarmatur | tre vægflanger, 900

Drain unit | three wall flanges, 900

06-10-2022

Art - no. 1001.0900

1:5



Unidrain A/S, Ejby Industrivej 40, DK-2600 Ejby
T +45 3910 1033 | www.unidrain.dk